



HALEY & ALDRICH, INC.  
6500 Rockside Road  
Suite 200  
Cleveland, OH 44131  
216.739.0555

August 28, 2025  
File No. 0212832

Associated Electric Cooperative, Inc.  
Thomas Hill Energy Center  
5693 Highway F  
Clifton Hill, Missouri, 65244

Attention: Mr. Ryan Bennett  
Environmental Analyst

Subject: 2025 Annual Inspection by a Qualified Professional Engineer  
Cell 001, Thomas Hill Energy Center  
Clifton Hill, Missouri

Dear Mr. Bennett:

Enclosed please find the 2025 Annual Inspection Report for the Associated Electric Cooperative, Inc. (AECI) Cell 001 located at the Thomas Hill Energy Center (THEC) in Clifton Hill, Missouri.

Haley & Aldrich, Inc. completed a site visit for the inspection of the CCR surface impoundment Cell 001 on July 29, 2025. This work was performed on behalf of AECI in accordance with the United States Environmental Protection Agency's Hazardous and Solid Waste Management System; Disposal of Coal Combustion Residuals from Electric Utilities, 40 Code of Federal Regulations Part 257, Subpart D, effective October 19, 2015, including subsequent revisions.

The scope of the work was to: i) complete a review of available information on the impoundment; ii) perform a visual inspection of the impoundment; and iii) prepare the enclosed report. Thank you for inviting us to complete this inspection and please feel free to contact us if you wish to discuss the contents of the report.

Sincerely yours,  
**HALEY & ALDRICH, INC.**

A handwritten signature in black ink, appearing to read 'Steven F. Putrich'.

Steven F. Putrich, P.E.  
Senior Associate – Principal Consultant

A handwritten signature in black ink, appearing to read 'Lee Saunders'.

Lee Saunders  
Project Manager

cc: Curtis Stundebek – AECI, Principal Engineer  
Jerret Fisher – AECI, Safety & Environmental Specialist  
Jason Pokorny – Haley & Aldrich, CCR Program Manager

Enclosures

**REPORT ON**  
**2025 ANNUAL INSPECTION BY A QUALIFIED PROFESSIONAL**  
**ENGINEER**  
**CELL 001 CCR SURFACE IMPOUNDMENT**  
**THOMAS HILL ENERGY CENTER**  
**CLIFTON HILL, MISSOURI**

By  
Haley & Aldrich, Inc.  
Cleveland, OH

For  
Associated Electric Cooperative, Inc.  
Thomas Hill Energy Center  
Clifton Hill, Missouri

File No. 0212832  
August 2025



## Table of Contents

	Page
<b>List of Figures</b>	<b>ii</b>
<b>1. Description of Project</b>	<b>1</b>
1.1 INTRODUCTION	1
1.1.1 Authority	1
1.1.2 Purpose of Work	1
1.2 DESCRIPTION OF PROJECT	1
1.2.1 Location	1
1.2.2 Owner/Operator	2
1.2.3 Background of the Impoundment	2
1.3 OPERATIONS AND MAINTENANCE PROCEDURES	2
<b>2. CCR Rule Inspection Report Requirements</b>	<b>4</b>
2.1 40 C.F.R. § 257.83(B)(1) – ANNUAL INSPECTIONS BY A QUALIFIED PROFESSIONAL ENGINEER	4
2.2 40 C.F.R. § 257.83(B)(2) – INSPECTION REPORT	5
<b>3. Inspection Summary and Recommendations</b>	<b>7</b>
3.1 OVERALL IMPOUNDMENT CONDITION OBSERVED	7
3.2 RECOMMENDATIONS	7
<b>4. Certification</b>	<b>8</b>

## List of Figures

Figure No.	Title
1	Project Location Map

# 1. Description of Project

## 1.1 INTRODUCTION

### 1.1.1 Authority

Haley & Aldrich, Inc. (Haley & Aldrich) was contracted by Associated Electric Cooperative, Inc. (AECI; the Owner) to perform an Annual Inspection of the CCR surface impoundment Cell 001 (pond or Unit) located at the AECI Thomas Hill Energy Center (THEC) in Clifton Hill, Missouri. This work was completed in accordance with the United States (U.S.) Environmental Protection Agency's (EPA's) Hazardous and Solid Waste Management System; Disposal of Coal Combustion Residuals (CCR) from Electric Utilities, 40 Code of Federal Regulations (C.F.R.) Part 257, Subpart D (Rule), effective October 19, 2015, including subsequent revisions, specifically 40 C.F.R. § 257.83(b).

### 1.1.2 Purpose of Work

The purpose of this annual inspection was to observe and evaluate the current condition of the CCR surface impoundment and to assess that the design, construction, operation, and maintenance of the CCR surface impoundment is consistent with recognized and generally accepted good engineering practice and standards. The visual inspection is intended to identify signs of distress or malfunction of the CCR surface impoundment, should they exist. This report addresses any signs of potential structural weaknesses and conditions that are disrupting (or have the potential to disrupt) the operations and safety of the CCR surface impoundment – that is, any deficiencies in the context of the CCR Rule, specifically 40 C.F.R. § 257.83(b)(5) – if identified.

The inspection is divided into three parts: i) a review of available information on the CCR surface impoundment (provided by AECI); ii) a visual inspection of the CCR surface impoundment (performed by Haley & Aldrich); and iii) preparation of the enclosed Haley & Aldrich report presenting observations and recommendations for any repairs or corrective measures, as deemed necessary.

## 1.2 DESCRIPTION OF PROJECT

### 1.2.1 Location

Cell 001 is a CCR surface impoundment located to the south of the Thomas Hill Energy Center in Clifton Hill, Missouri off U.S. Highway F as shown on **Figure 1**. The plant and impoundment have restricted access, with full-time security. The general configuration of the impoundment is shown in **Figure 1**.

### 1.2.2 Owner/Operator

The CCR surface impoundment Cell 001 is owned, operated, and maintained by AECl. Additional details are provided below.

	Impoundment Owner/Caretaker
Name	Associated Electric Cooperative, Inc. Thomas Hill Energy Center
Mailing Address	5693 Highway F
Town, State Zip	Clifton Hill, MO 65244

### 1.2.3 Background of the Impoundment

Cell 001 was originally designed by Burns & McDonnell in 1984 and was constructed shortly thereafter. It operated as part of the “Ash Pond 1” multi-unit wastewater treatment system at THEC and was previously used for settling and temporary wet storage of bottom ash and boiler slag sluiced from Thomas Hill Units 1 and 2. Historically, CCR sluice water was pumped from the power plant to the southwest corner of Cell 001 through two approximate 14-in. diameter pipes. Suspended solids settled in the impoundment, which were then removed and placed onto the adjacent Cell 001 Dewatering Pad and transported for disposal or beneficial use.

In 2020-2021, the Concrete Dewatering Tank (CDT) was constructed directly east of Cell 001 and now provides settling treatment for CCR wastestreams previously managed in Cell 001; it recirculates a majority of sluice water back to the plant in accordance with applicable effluent limitations guidelines requirements.

Cell 001 ceased receipt of CCR and non-CCR waste streams generated by THEC as of September 2, 2021 and AECl issued the notification of intent to initiate closure of a CCR surface impoundment on September 15, 2021. Removal of CCR material was completed in October 2021 and the area was reconfigured as a secondary (non-CCR) impoundment to support management of CDT blowdown and other low volume waste water discharges. Cell 001 remains in closure at the time of inspection.

## 1.3 OPERATIONS AND MAINTENANCE PROCEDURES

Cell 001 is operated and maintained by AECl personnel. Current operations and maintenance activities include regulating water levels in the impoundment, regulating and monitoring discharge from the CDT to Cell 001, regularly mowing grass, seeding of thinly vegetated areas, control of woody growth, and repair of erosions as needed, and weekly inspections.

AECl personnel monitor and inspect the impoundment at least once every seven days and maintain inspection results in the operating record as required by the CCR Rule. These weekly inspections include a visual inspection and review of:

- Run-on and run-off controls (including erosion and sediment controls, where applicable);
- Freeboard and pool area;
- Vegetation around the impoundment and embankments;
- Outlet structure and stop logs (including principal spillway); and
- Other indicators of structural stability of the impoundment.

Haley & Aldrich reviewed weekly inspection records for 2025 as part of the annual inspection, which noted all items as meeting expectations (i.e., no need for improvement).

## 2. CCR Rule Inspection Report Requirements

### 2.1 40 C.F.R. § 257.83(b)(1) – ANNUAL INSPECTIONS BY A QUALIFIED PROFESSIONAL ENGINEER

*40 C.F.R. §257.83(b)(1)(i): A review of available information regarding the status and condition of the CCR unit, including, but not limited to, files available in the operating record (e.g., CCR unit design and construction information required by §§ 257.73(c)(1) and 257.74(c)(1), previous periodic structural stability assessments required under §§ 257.73(d) and 257.74(d), the results of inspections by a qualified person, and results of previous annual inspections).*

Seven-day inspection records performed by qualified AECl staff during 2025 and previous annual inspections were reviewed as part of this annual inspection. Haley & Aldrich spoke with AECl personnel during the site visit on July 29, 2025 regarding the background, operations, and maintenance of the impoundment. Information provided by AECl personnel has been incorporated into this report.

The 2024 Annual Inspection performed by Gredell Engineering Resources, Inc. (GER) on August 15, 2024, listed minor erosion of the gravel parking lot southwest of the CDT and the gravel ramp accessing the bottom of Cell 001. GER also noted sparse vegetation in two separate areas around the Unit.

The following documents were also reviewed regarding the status and condition of the CCR unit:

- Fugitive Dust Control Plan (October 2015) and Annual Fugitive Dust Control Reports;
- Inflow Design Flood Control System Plan (October 2021);
- Annual Groundwater Monitoring and Corrective Action Reports;
- Period Hazard Potential Classification Assessment (October 2021);
- Periodic Structural Stability Assessment (October 2021);
- Inspection Deficiencies and Remedies Memo (May 2021);
- History of Construction (October 2016); and
- Any work orders generated as a result of the inspections.

Any comments and recommendations resulting from these reviews are provided in **Section 3**, below.

*40 C.F.R. §257.83(b)(1)(ii): A visual inspection of the CCR unit to identify signs of distress or malfunction of the CCR unit and appurtenant structures.*

There were no visible signs of distress or malfunction of the CCR surface impoundment Cell 001 or its appurtenant structures at the time of the inspection. The impoundment did not show signs of deviation from the original design.

*40 C.F.R. §257.83(b)(1)(iii): A visual inspection of any hydraulic structures underlying the base of the CCR unit or passing through the dike of the CCR unit for structural integrity and continued safe and reliable operation.*



The outlet structure from Cell 001 consists of a rectangular concrete decant structure equipped with 60 in. wide concrete stop logs that discharges to a 30-in. diameter reinforced concrete pipe which appeared to be intact, stable, and properly aligned. No sediment or debris were observed at either end of the outlet pipe.

## 2.2 40 C.F.R. § 257.83(b)(2) – INSPECTION REPORT

*The qualified professional engineer must prepare a report following each inspection that addresses the following:*

40 C.F.R. §257.83(b)(2)(i): *Any changes in geometry of the impounding structure since the previous annual inspection.*

No changes in geometry of the impounding structure since the previous annual inspection were observed. There was no discernible sag, slumping, bulging or other geometric indications of adverse embankment or slope performance. The embankments showed no signs of instability or unusual movement and had no noticeable deviation from design.

40 C.F.R. §257.83(b)(2)(ii): *The location and type of existing instrumentation and the maximum recorded readings of each instrument since the previous annual inspection.*

There is no instrumentation pertinent to Cell 001.

40 C.F.R. §257.83(b)(2)(iii): *The approximate minimum, maximum, and present depth and elevation of the impounded water and CCR since the previous annual inspection.*

Haley & Aldrich is not aware of the maximum depth and elevation of the impounded water and CCR since the previous annual inspection. At the time of the inspection, there was no water or CCR present within the impoundment.

40 C.F.R. §257.83(b)(2)(iv): *The storage capacity of the impounding structure at the time of the inspection.*

The remaining storage capacity of the CCR surface impoundment Cell 001 at the time of the inspection is approximately 9 acre-feet.

40 C.F.R. §257.83(b)(2)(v): *The approximate volume of the impounded water and CCR at the time of the inspection.*

At the time of the inspection there was no water or CCR observed within the impoundment.

40 C.F.R. §257.83(b)(2)(vi): *Any appearances of an actual or potential structural weakness of the CCR unit, in addition to any existing conditions that are disrupting or have the potential to disrupt the operation and safety of the CCR unit and appurtenant structures.*

There were no appearances of actual or potential structural weakness of the CCR surface impoundment Cell 001. There were no observed conditions disrupting or having the potential to disrupt the operation and safety of the CCR unit and appurtenant structures.

40 C.F.R. §257.83(b)(2)(vii): *Any other change(s) which may have affected the stability or operation of the impounding structure since the previous annual inspection.*

At the time of the inspection there were no discernible changes which could have affected the stability or operation of Cell 001 since the previous inspection.

### 3. Inspection Summary and Recommendations

#### 3.1 OVERALL IMPOUNDMENT CONDITION OBSERVED

Overall, the CCR surface impoundment was observed to be stable and broadly consistent with recognized and generally accepted good engineering standards. Visual inspection of the existing conditions of the impoundment did not indicate any actual or potential structural weakness of the impoundment, or any actual or potential disruptions to normal operations and safety of the impoundment. No changes in overall impoundment geometry were noted since the previous annual inspection.

The following items were noted during our site visit. We recommend these be closely reviewed during weekly inspections to proactively mitigate and ensure they do not develop into potential interruptions in the future:

- Rutting present in the vicinity of the impoundment; and
- Minor puddles in the dewatering pad area.

#### 3.2 RECOMMENDATIONS

Although no deficiencies were identified at the time of the inspection, as referenced 40 C.F.R. § 257.83(b)(5) – *if a deficiency or release is identified during an inspection, the owner or operator must remedy the deficiency or release as soon as feasible and prepare documentation detailing the corrective measures taken* – we recommend the following measures be undertaken to address items listed in **Section 3.1** in support of on-going maintenance and operational activities:

- Monitor and fill in/ level out the rutting in the vicinity of the impoundment to ensure proper access is maintained.
- Monitor and fill eroded areas with additional aggregate material to prevent further degradation of the surface, as necessary.

## 4. Certification

The assessment of the general condition of the CCR surface impoundment Cell 001 is based upon available data and visual observation as described herein. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of this report.

In reviewing this report, it should be recognized that the described condition of the CCR surface impoundment is based on visual observations of field conditions at the time of inspection, along with other data made available by AECl to the inspection team. It is important to note that the condition of an impoundment depends on numerous and constantly changing internal and external conditions and is evolutionary in nature. It would be incorrect to assume that the present condition of the impoundment will continue to represent the condition of the impoundment at some point in the future.

In my professional opinion and based on the information presented in this report, the physical condition and ongoing operations and maintenance of the impoundment Cell 001 at the AECl THEC is consistent with recognized and generally accepted good engineering standards and practice.

Signed:



Qualified Professional Engineer

Print Name: Steven F. Putrich

Missouri License No.: 2014035813

Title: Principal Consultant


Company: Haley & Aldrich, Inc.

Professional Engineer's Seal and date:



## FIGURES





MAP SOURCE:  
PRAIRIE HILL AND COLLEGE MOUND QUADRANGLES  
MISSOURI, 7.5-MINUTE SERIES, 2021



**HALEY  
ALDRICH**

ANNUAL CCR SURFACE IMPOUNDMENT INSPECTION  
ASSOCIATED ELECTRIC COOPERATIVE, INC.  
THOMAS HILL ENERGY CENTER - CELL 001  
CLIFTON HILL, MISSOURI

## PROJECT LOCATION MAP

APPROXIMATE SCALE: 1IN = 2000 FT  
AUGUST 2025

FIGURE 1