

Annual CCR Surface Impoundment PE Inspection

Pond 003
New Madrid Power Plant
New Madrid, MO

Associated Electric Cooperative, Inc.

Inspection

Visual Inspection

On January 11, 2019, a visual inspection of the surface impoundment was completed. The visual inspection included both a visual inspection of the CCR impoundment to identify signs of distress or malfunction and a visual inspection of the hydraulic structures for structural integrity. The following subsections and enclosed inspection report describe the conditions observed during the inspection.

Changes in Geometry

There have been no changes to the geometry of the impounding structure since the previous annual inspection.

Instrumentation Readings

Piezometers/monitoring wells are located along the crest of the dikes of Pond 003. The piezometers/groundwater monitoring wells were installed for purposes of monitoring groundwater and are not monitored for structural stability purposes. No readings were taken. No other instrumentation was identified as part of the inspection.

Impounded Water Depth

On the inspection date, the pond water elevation was recorded at 299.5 ft. The concrete stop logs in the decant structure have been set at an approximate elevation of 299.5 ft and have not been adjusted. This is equivalent to a depth of approximately 14 feet.

Storage Capacity

The remaining storage capacity of the impoundment was approximated to be 167 acre-ft. As part of normal operation, ash collected in the pond is periodically disposed of in the Utility Waste Landfill and a very minimal amount of ash accumulates in the pond.

Volumes

The impounded water is approximated to be 48 acre-ft. The impounded CCR volume was approximated to be 1768 acre-ft. As part of normal operation, ash collected in the pond is periodically disposed of in the Utility Waste Landfill and a very minimal amount of ash accumulates in the pond.

Inspection for Structural Weaknesses

The impoundment was visually inspected for any appearances of an actual or potential structural weakness of the CCR unit. The visual inspection did not indicate any deficiencies. Details of this inspection can be found in the enclosed inspection checklist.

Certification


The assessment of the general condition of the surface impoundment is based upon available data and visual observation as required by 40 CFR 257.83 (b) – Inspection Requirements for CCR Surface Impoundments. In reviewing this report, it should be realized that the described condition of the surface impoundment is based on observations of field conditions at the time of inspection. Conditions of surface impoundments depend on numerous internal and external conditions, therefore it should be noted that the estimates and observations only represent the conditions at the time of inspection.

Signed: Lowell Dennis Cox

Print Name: Lowell Dennis Cox

Missouri License Number: 2001004579

Date: 1/17/2019



Dam/Impoundment Evaluation Summary Detail Sheet

1. NID ID:	N/A	4. Inspection Date:	January 11, 2019
2. Dam Name:	Pond 003	5. Last Insp. Date:	January 19, 2018
3. Dam Location:	41 St. Jude Park, Marston, MO	6. Next Inspection:	
7. Inspector:	Dennis Cox, P. E.		
8. Consultant:	N/A		
9. Hazard Code:	9a. Is Hazard Code Change Requested?		
10. Insp. Frequency: #N/A	11. Overall Physical Condition of Dam:		
12. Spillway Capacity (% SDF)			
E1. Design Methodology:	4	E7. Low-Level Discharge Capacity:	4
E2. Level of Maintenance:	4	E8. Low-Level Outlet Physical Condition:	4
E3. Emergency Action Plan:	5	E9. Spillway Design Flood Capacity:	N/A
E4. Embankment Seepage:	5	E10. Overall Physical Condition of the Dam:	5
E5. Embankment Condition:	5	E11. Estimated Repair Cost:	N/A
E6. Concrete Condition:	5		

Evaluation Description

E1: DESIGN METHODOLOGY

1. Unknown Design – no design records available
2. No design or post-design analyses
3. No analyses, but dam features appear suitable
4. Design or post design analysis show dam meets most criteria
5. State of the art design – design records available & dam meets all criteria

E2: LEVEL OF MAINTENANCE

1. Dam in disrepair, no evidence of maintenance, no O&M manual
2. Dam in poor level of upkeep, very little maintenance, no O&M manual
3. Dam in fair level of upkeep, some maintenance and standard procedures
4. Adequate level of maintenance and standard procedures
5. Dam well maintained, detailed maintenance plan that is executed

E3: EMERGENCY ACTION PLAN

1. No plan or idea of what to do in the event of an emergency
2. Some idea but no written plan
3. No formal plan but well thought out
4. Available written plan that needs updating
5. Detailed, updated written plan available and filed with MADCR, annual training

E4: SEEPAGE (Embankments, Foundations, & Abutments)

1. Severe piping and/or seepage with no monitoring
2. Evidence of monitored piping and seepage
3. No piping but uncontrolled seepage
4. Minor seepage or high volumes of seepage with filtered collection
5. No seepage or minor seepage with filtered collection

E5: EMBANKMENT CONDITION

1. Severe erosion and/or large trees
2. Significant erosion or significant woody vegetation
3. Brush and exposed embankment soils, or moderate erosion
4. Unmaintained grass, rodent activity and maintainable erosion
5. Well maintained healthy uniform grass cover

E6: CONCRETE CONDITION

1. Major cracks, misalignment, discontinuities causing leaks, seepage or stability concerns
2. Cracks with misalignment inclusive of transverse cracks with no misalignment but with potential for significant structural degradation
3. Significant longitudinal cracking and minor transverse cracking
4. Spalling and minor surface cracking
5. No apparent deficiencies

E7: LOW-LEVEL OUTLET DISCHARGE CAPACITY

1. No low level outlet, no provisions (e.g. pumps, siphons) for emptying pond
2. No operable outlet, plans for emptying pond, but no equipment
3. Outlet with insufficient drawdown capacity, pumping equipment available
4. Operable gate with sufficient drawdown capacity
5. Operable gate with capacity greater than necessary

E8: LOW-LEVEL OUTLET PHYSICAL CONDITION

1. Outlet inoperative needs replacement, non-existent or inaccessible
2. Outlet inoperative needs repair
3. Outlet operable but needs repair
4. Outlet operable but needs maintenance
5. Outlet and operator operable and well maintained

E9: SPILLWAY DESIGN FLOOD CAPACITY

1. 0 - 50% of the SDF or unknown
2. 50-90% of the SDF
3. 90 - 100% of the SDF
4. >100% of the SDF with actions required by caretaker (e.g. open outlet)
5. >100% of the SDF with no actions required by caretaker

E10: OVERALL PHYSICAL CONDITION OF DAM

1. UNSAFE – Major structural, operational, and maintenance deficiencies exist under normal operating conditions
2. POOR – Significant structural, operation and maintenance deficiencies are clearly recognized under normal loading conditions
3. FAIR - Significant operational and maintenance deficiencies, no structural deficiencies. Potential deficiencies exist under unusual loading conditions that may realistically occur. Can be used when uncertainties exist as to critical parameters
4. SATISFACTORY - Minor operational and maintenance deficiencies. Infrequent hydrologic events would probably result in deficiencies.
5. GOOD - No existing or potential deficiencies recognized. Safe performance is expected under all loading including SDF

E11: ESTIMATED REPAIR COST

Estimation of the total cost to address all identified structural, operational, maintenance deficiencies. Cost shall be developed utilizing standard estimating guides and procedures

Changes/Deviations to Database Information since Last Inspection

IMPOUNDMENT/DAM DEFICIENCIES

Impoundment/Dam
Name
NID ID #

Deficiency No. **Description**

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	

DAM SAFETY INSPECTION CHECKLIST

NAME OF DAM:	Pond 003	STATE ID #:	MO-0001171
REGISTERED: (YES/NO)	No	NID ID #:	N/A
STATE SIZE CLASSIFICATION:	N/A	STATE HAZARD CLASSIFICATION:	TBD
		CHANGE IN HAZARD CLASSIFICATION:	
		REQUESTED?: (YES/NO)	No
<u>DAM LOCATION INFORMATION</u>			
CITY/TOWN:	New Madrid	COUNTY/STATE:	<i>New Madrid/Missouri</i>
DAM LOCATION:	41 St. Jude Park, Marston, MO (street address if known)	ALTERNATE DAM NAME:	N/A
USGS QUAD:	New Madrid, MO-KY	LAT:	36° 30.4' N
DRAINAGE BASIN:	N/A	RIVER:	Mississippi River
IMPOUNDMENT NAME(S):	Unlined Ash Pond (003 Pond)	<u>GENERAL DAM INFORMATION</u>	
TYPE OF DAM:	Earthen Incised and Bermed	OVERALL LENGTH (FT):	9300
PURPOSE OF DAM:	Sedimentation and Storage Basin	NORMAL POOL STORAGE (ACRE-FT):	
YEAR BUILT:	1972	MAXIMUM POOL STORAGE (ACRE-FT):	1707
STRUCTURAL HEIGHT (FT):	20	EL. NORMAL POOL (FT):	302.0
HYDRAULIC HEIGHT (FT):	8	EL. MAXIMUM POOL (FT):	307.0 (minimum crest elevation)
RESERVOIR SURFACE AREA (ACRES):	110	WINTER DRAWDOWN (FT BELOW NORMAL POOL)	0.0
PUBLIC ROAD ON CREST:	No	DRAWDOWN VOL. (AC-FT)	0.0
PUBLIC BRIDGE OVER SPILLWAY	No		

NAME OF DAM:	Pond 003	STATE ID #:	MO-0001171
INSPECTION DATE:	<u>January 11, 2019</u>	NID ID #:	N/A
<u>INSPECTION SUMMARY</u>			
DATE OF INSPECTION:	<u>January 11, 2019</u>	DATE OF PREVIOUS INSPECTION:	<u>January 19, 2018</u>
TEMPERATURE/WEATHER:	Cloudy, 32 Degrees	ARMY CORPS PHASE I: (YES/NO)	If YES, date _____
CONSULTANT:	<u>N/A</u>	PREVIOUS ALT. PHASE I: (YES/NO)	If YES, date _____
BENCHMARK/DATUM:	<u>NAVD88</u>		
OVERALL PHYSICAL CONDITION OF DAM:	_____	DATE OF LAST REHABILITATION:	<u>N/A</u>
SPILLWAY CAPACITY:	_____	EL. TAILWATER DURING INSP.:	<u>299.5 ft</u>
EL. POOL DURING INSP.:	<u>299.5 ft</u>	<u>PERSONS PRESENT AT INSPECTION</u>	
<u>NAME</u>	<u>TITLE/POSITION</u>	<u>REPRESENTING</u>	
Dennis Cox	<u>Senior Plant Engineer</u>	<u>ABCI</u>	_____

NAME OF DAM:	Pond 003	STATE ID #:	MO-0001171
INSPECTION DATE:	January 11, 2019	NID ID #:	N/A
OWNER:	ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE EMERGENCY PH. # FAX EMAIL OWNER TYPE	CARETAKER: Associated Electric Cooperative, Inc. Dennis Cox - Senior Plant Eng. P.O. Box 156 New Madrid, MO 63869 TOWN, STATE, ZIP PHONE EMERGENCY PH. # FAX EMAIL	ORGANIZATION NAME/TITLE STREET TOWN, STATE, ZIP PHONE EMERGENCY PH. # FAX EMAIL
PRIMARY SPILLWAY TYPE	Decant Structure	SPILLWAY CAPACITY (CFS)	N/A
SPILLWAY LENGTH (FT)	N/A	AUX. SPILLWAY CAPACITY (CFS)	N/A
AUXILIARY SPILLWAY TYPE	N/A	OUTLET(S) CAPACITY (CFS)	Unknown
NUMBER OF OUTLETS	One	TOTAL DISCHARGE CAPACITY (CFS)	Unknown
TYPE OF OUTLETS	One Decant	SPILLWAY DESIGN FLOOD (PERIOD/CFS)	Unknown
DRAINAGE AREA (SQ MI)	0.17		
HAS DAM BEEN BREACHED OR OVERTOPPED? (YES/NO):	No	IF YES, PROVIDE DATE(S):	
FISH LADDER (LIST TYPE IF PRESENT)	Unknown		
DOES CREST SUPPORT PUBLIC ROAD? (YES/NO)	No	IF YES, ROAD NAME:	
PUBLIC BRIDGE WITHIN 50' OF DAM? (YES/NO):	No	IF YES, ROAD/BRIDGE NAME: MHD BRIDGE NO. (IF APPLICABLE):	

NAME OF DAM: <u>Pond 003</u>	STATE ID #: <u>MO-0001171</u>				
INSPECTION DATE: <u>January 11, 2019</u>	NID ID #: <u>N/A</u>				
EMBANKMENT (CREST)					
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
CREST	1. SURFACE TYPE				
	2. SURFACE CRACKING	None observed	X		
	3. SINKHOLES, ANIMAL BURROWS	None observed	X		
	4. VERTICAL ALIGNMENT (DEPRESSIONS)	None observed	X		
	5. HORIZONTAL ALIGNMENT	None observed	X		
	6. RUTS AND/OR PUDDLES	None observed	X		
	7. VEGETATION (PRESENCE/CONDITION)	None observed	X		
	8. ABUTMENT CONTACT	None observed	X		
ADDITIONAL COMMENTS:					

NAME OF DAM: <u>Pond 003</u>	STATE ID #: <u>MO-0001171</u>					
INSPECTION DATE: <u>January 11, 2019</u>	NID ID #: <u>N/A</u>					
EMBANKMENT (D/S SLOPE)						
D/S SLOPE	AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
	1. WET AREAS (NO FLOW)		None observed	X		
	2. SEEPAGE		None observed	X		
	3. SLIDE, SLOUGH, SCARP		None observed	X		
	4. EMB.-ABUTMENT CONTACT		N/A			
	5. SINKHOLE/ANIMAL BURROWS		None observed	X		
	6. EROSION		None observed	X		
	7. UNUSUAL MOVEMENT		None observed	X		
	8. VEGETATION (PRESENCE/CONDITION)		Slopes are mowed grass.	X		
ADDITIONAL COMMENTS:						

NAME OF DAM: <u>Pond 003</u>	STATE ID #: <u>MO-0001171</u>			
INSPECTION DATE: <u>January 11, 2018</u>	NID ID #: <u>N/A</u>			
EMBANKMENT (U/S SLOPE)				
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION MONITOR	REPAIR
U/S SLOPE	1. SLIDE, SLOUGH, SCARP	None observed	X	
	2. SLOPE PROTECTION TYPE AND COND.	None observed	X	
	3. SINKHOLE/ANIMAL BURROWS	None observed	X	
	4. EMB.-ABUTMENT CONTACT	None observed	X	
	5. EROSION	None observed	X	
	6. UNUSUAL MOVEMENT	None observed	X	
	7. VEGETATION (PRESENCE/CONDITION)	None observed	X	
<p>ADDITIONAL COMMENTS: Ash has been stockpiled to an elevation equal to the embankment in the Northern portion of the Unlined Ash Pond. Therefore, the upstream slope was covered by ash and not visible for inspection.</p>				

NAME OF DAM:	Pond 003	STATE ID #:	MO-0001171
INSPECTION DATE:	January 11, 2019	NID ID #:	N/A
DOWNSTREAM AREA			
AREA INSPECTED	CONDITION	OBSERVATIONS	
D/S AREA	1. ABUTMENT LEAKAGE	None Present	
	2. FOUNDATION SEEPAGE	None Present	
	3. SLIDE, SLOUGH, SCARP	None Present	
	4. WEIRS	None Present	
	5. DRAINAGE SYSTEM	None Present	
	6. INSTRUMENTATION	None Present	
	7. VEGETATION	Grass less than 6"	
	8. ACCESSIBILITY	Gravel access road along crest. Full time security and fence	
	9. DOWNSTREAM HAZARD DESCRIPTION		
	10. DATE OF LAST EAP UPDATE		
ADDITIONAL COMMENTS:			

NAME OF DAM: <u>Pond 003</u>	STATE ID #: <u>MO-0001171</u>				
INSPECTION DATE: <u>January 11, 2019</u>	NID ID #: <u>N/A</u>				
PRIMARY SPILLWAY					
AREA INSPECTED	CONDITION	OBSERVATIONS	NO ACTION	MONITOR	REPAIR
SPILLWAY TYPE		Decant structure	X		
WEIR TYPE		Concrete stoplogs in decant structure	X		
SPILLWAY CONDITION		Fair	X		
SPILLWAY TRAINING WALLS		None present	X		
SPILLWAY CONTROLS AND CONDITION		None present	X		
UNUSUAL MOVEMENT		None present	X		
APPROACH AREA		Fair	X		
DISCHARGE AREA		Fair	X		
DEBRIS		None present	X		
WATER LEVEL, AT TIME OF INSPECTION		299.5'	X		
ADDITIONAL COMMENTS:					

NAME OF DAM:	Pond 003	STATE ID #:	MO-0001171
INSPECTION DATE:	January 11, 2019	NID ID #:	N/A
OUTLET WORKS			
AREA INSPECTED	CONDITION	OBSERVATIONS	
OUTLET WORKS	TYPE	Outlet unable to be inspected.	
	INTAKE STRUCTURE	Decant structure with stoplogs	
	TRASHRACK	N/A	
	PRIMARY CLOSURE	N/A	
	SECONDARY CLOSURE	N/A	
	CONDUIT	N/A	
	OUTLET STRUCTURE/HEADWALL	Fair	
	EROSION ALONG TOE OF DAM	None	
	SEEPAGE/LEAKAGE	None	
	DEBRIS/BLOCKAGE	None	
	UNUSUAL MOVEMENT	None	
	DOWNTSTREAM AREA	Regularly mowed.	
MISCELLANEOUS			
ADDITIONAL COMMENTS:			

NAME OF DAM: Pond 003

INSPECTION DATE: January

STATE ID #: MO-0001171

N/A

STATE ID #: MO-0001171

N/A

UNDERLYING HYDRAULIC STRUCTURES/PIPES

ADDITIONAL COMMENTS:

Note: Use additional sheets for additional outlets.